



PD TEESPORT LIMITED

NOTICE TO MARINERS NO.21 OF 2019

Issued by the Harbour Master on 07 August

NORTH-EAST COAST OF ENGLAND

RIVER TEES

TRANSPORTER BRIDGE

PD Teesport hereby gives notice that a risk of corroded steel items falling from the Transporter Bridge has been identified.

The risk has been assessed as being extremely low; however, as an additional safeguard, Mariners are advised not to pass under the Transporter Bridge with crew members on the open decks.

A further inspection of the Bridge will be carried out as soon as possible.

NOTE: Owners, Agents and Charterers should ensure that the contents of this Notice are made known to Masters or persons in charge of their vessels or craft.