



PD TEESPORT LIMITED

NOTICE TO MARINERS NO.31 OF 2021

Updated by the Harbour Master on 06 July

NORTH-EAST COAST OF ENGLAND

RIVER TEES

TRANSPORTER BRIDGE

PD Teesport hereby draws the attention of Mariners to concerns regarding the rusting of struts/angles on the Bridge, some of which need to be either taken down/securely repaired and re-inspected.

PD Teesport have been advised that, given the summer conditions and the fact that the struts/angles have been in that state for some time, the risk of them coming loose at this moment is low.

PD Teesport would advise that, wherever possible, crew members should remain off the open deck when passing under the Bridge.

Work to address this has now commenced, for an initial period of 1 month, during which time the safety boat "Katana" will be on station.

Further information is available from TEES VTS on VHF Channel 14 or telephone 01642 277205.

NOTE: Owners, Agents and Charterers should ensure that the contents of this Notice are made known to Masters or persons in charge of their vessels or craft.

* * *