

PD TEESPORT LIMITED

# NOTICE TO MARINERS NO.33 OF 2022

Issued by the Harbour Master on 04 April

NORTH-EAST COAST OF ENGLAND

TEES BAY

## LOCAL AIDS TO NAVIGATION

PD Teesport hereby gives notice that the following local aid to navigation is currently displaying the incorrect light character (Fixed White Light instead of Mo(A)5s8M).

- Tees Approach Buoy            54°40.600'N   001°04.000'W

Estimated time for reinstatement is 1 week.

Further information is available from TEES VTS on VHF Channel 14 or telephone 01642 277205.

**NOTE:** Owners, Agents and Charterers should ensure that the contents of this Notice are made known to Masters or persons in charge of their vessels or craft.

\* \* \*